

NEWS BULLETIN

RELEASE DATE: December 2020

ONE SMALL SPIKE!

One small steel spike in the ground by our builders and one prayed through step of faith by the BBC church fellowship.

Its mid-week in mid-November and a small van arrives in York Road with two technicians and some sophisticated surveying equipment. Their mission is to precisely pinpoint the front left corner of the new phase two worship hall.

Using previous key location points that were installed during the erection of phase one and measuring off using digital theodolites they drove a series of hardened steel pins into the side path. These markers are very easily camouflaged amongst the paving blocks so they are highlighted by pink fluorescent spray

Why was this done in November? The reason is that the builders need to establish with total accuracy the line of the side wall for the new worship hall in relation to the retaining wall of the side access road. This gives them an idea of the space they have for the groundworks they will carry out.

Now lots of plans and procedures are underway ready for the builders to take over the site on Monday January the 13th and the asbestos survey stage will commence. The demolition notice has been sent to BCP Council.



painted circles – all ready for January!

